




roughly coursed rubble walling.

Above: section AA
Hood moulding.



S.W. QUOIN L&S WORK,
shown in relative
(actual) position to archway.

CHURCH of ST. ANDREW.
BRIGSTOCK.
ANGLO-SAXON ARCH,
to tower/nave.