

### St. Nicholas, Worth, Sussex.

Date of building circa 1050, and possibly earlier (H.Taylor).  
 This page, clockwise from top left.

1. General view taken from the NW.
2. West wall of north transept.
3. East wall of south transept.
4. N wall of nave, note absence of pilaster strips, blocked doorway, and the remarkable double window of which 3 survive out of four.
5. As pic 4 and note the coursed stonework in contrast to the random rubble of the remainder of the exterior of the church. To the left the W wall of N transept.
6. The west front.
7. *Left.* The E wall of S transept and the chancel (restored 1871) to the right. 8. *Right.* The westernmost part of the S wall of the nave.

Nikon

# St. Nicholas, Worth.


This page—pilaster strips and windows.



Nikon



**St. Nicholas, Worth.**  
This page — the fine chancel arch.



Nikon



# St. Nicholas, Worth.

This page — view clockwise from top right.

1. The archway to S transept (its jambs and imposts are almost wholly restorations) viewed from inside nave.
2. As 1, but viewed from inside transept.
3. N transept archway viewed from nave.
4. Blocked N doorway.
5. Tall S doorway with later inserted medieval doorway.
6. N transept archway viewed from SW. 7. As 6 but west jamb/impost.

